

Service Repair Sheet SRS67765

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Duncan Clark

Company/ Hospital Name

JFD

Department

Position

Direct Phone

01224 740145

General Phone

Opera Account

VST036

Email

Order Number

Date Received

16/Mar/2021

Booked in By

Catherine Spence

Main Company

VandagraphST

Type Return

Notes 16/Mar/2021 Catherine Spence

16/Mar/2021 Catherine Spence

16/Mar/2021 Catherine Spence

3 X sensors s/n 100477,100478,100476

Corroded

16/Mar/2021 Catherine Spence

received in dated 2018-12

Ready For quote

Repair Complete Signed

C. Spence 29.6.2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33462	Oxygen Sensor VST	8010050	100477	2
SRN33463	Oxygen Sensor VST	8010050	100478	2
SRN33464	Oxygen Sensor VST	8010050	100476	2

0140010 x 3 @ £0.

S/N's, SRS, SRN.

Out of Warranty.

Returned as instructed by Duncan Clark