

Service Repair Sheet 67758

Contact Name	Jim McKay
Company/ Hospital Name	JFD Limited
Position	Senior QC Inspector
General Phone	01224 740 145
Opera Account	VST036
Date Received	06/Apr/2021
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN33551	8010050	101940	Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)

Sensor reported as failed mag range testing, this is outside of the scope of warranty. Sensor to be returned to JFD as instructed by Duncan Clark.

Repair	Ref	S/N	Equipment Type	
SRN33552	8010050	101941	Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	
SRN33553	8010050	101942	Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	
SRN33554	8010050	101947	Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	
SRN33555	8010050	101948	Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	
SRN33556	8010050	101949	Oxygen Sensor VST	End Of Life Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	
SRN33557	8010050	101986	Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	
SRN33558	8010050	101987	Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)

Service Repair Sheet 67758

Contact Name	Jim McKay
Company/ Hospital Name	JFD Limited
Position	Senior QC Inspector
General Phone	01224 740 145
Opera Account	VST036
Date Received	06/Apr/2021
Booked in By	Robert Connor

Repair SRN33559	Ref 8010050	S/N 101917	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33560	Ref 8010050	S/N 101993	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33561	Ref 8010050	S/N 101994	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33562	Ref 8010050	S/N 101995	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33563	Ref 8010050	S/N 101979	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33564	Ref 8010050	S/N 101906	Equipment Type Oxygen Sensor VST	End Of Life Time :0 Hour(s)
Repair SRN33565	Ref 8010050	S/N 101907	Equipment Type Oxygen Sensor VST	End Of Life Time :0 Hour(s)
Repair SRN33566	Ref 8010050	S/N 101954	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33567	Ref 8010050	S/N 101955	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)

Service Repair Sheet 67758

Contact Name	Jim McKay
Company/ Hospital Name	JFD Limited
Position	Senior QC Inspector
General Phone	01224 740 145
Opera Account	VST036
Date Received	06/Apr/2021
Booked in By	Robert Connor

Repair SRN33568	Ref 8010050	S/N 101928	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33569	Ref 8010050	S/N 101929	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33570	Ref 8010050	S/N 101963	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33571	Ref 8010050	S/N 101914	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33572	Ref 8010050	S/N 101915	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33573	Ref 8010050	S/N 101910	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33574	Ref 8010050	S/N 101911	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33575	Ref 8010050	S/N 101968	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33576	Ref 8010050	S/N 101969	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)

Service Repair Sheet 67758

Contact Name	Jim McKay
Company/ Hospital Name	JFD Limited
Position	Senior QC Inspector
General Phone	01224 740 145
Opera Account	VST036
Date Received	06/Apr/2021
Booked in By	Robert Connor

Repair SRN33577	Ref 8010050	S/N 101934	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33578	Ref 8010050	S/N 101935	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33579	Ref 8010050	S/N 101936	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33580	Ref 8010050	S/N 101909	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33581	Ref 8010050	S/N 101919	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33582	Ref 8010050	S/N 101960	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33583	Ref 8010050	S/N 101975	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33584	Ref 8010050	S/N 101973	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33585	Ref 8010050	S/N 101970	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)

Service Repair Sheet 67758

Contact Name	Jim McKay
Company/ Hospital Name	JFD Limited
Position	Senior QC Inspector
General Phone	01224 740 145
Opera Account	VST036
Date Received	06/Apr/2021
Booked in By	Robert Connor

Repair SRN33586	Ref 8010050	S/N 101991	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33587	Ref 8010050	S/N 101932	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33588	Ref 8010050	S/N 101921	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33589	Ref 8010050	S/N 101981	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33590	Ref 8010050	S/N 101939	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33591	Ref 8010050	S/N 101923	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33592	Ref 8010050	S/N 101989	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33593	Ref 8010050	S/N 101966	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33594	Ref 8010050	S/N 101958	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)

Service Repair Sheet 67758

Contact Name	Jim McKay
Company/ Hospital Name	JFD Limited
Position	Senior QC Inspector
General Phone	01224 740 145
Opera Account	VST036
Date Received	06/Apr/2021
Booked in By	Robert Connor

Repair SRN33595	Ref 8010050	S/N 102001	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33596	Ref 8010050	S/N 102005	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33597	Ref 8010050	S/N 102009	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33598	Ref 8010050	S/N 102010	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33599	Ref 8010050	S/N 102019	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33600	Ref 8010050	S/N 102021	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33601	Ref 8010050	S/N 102022	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33602	Ref 8010050	S/N 102024	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)
Repair SRN33603	Ref 8010050	S/N 102025	Equipment Type Oxygen Sensor VST	Return Unrepaired Time :0 Hour(s)

Service Repair Sheet 67758

Contact Name	Jim McKay
Company/ Hospital Name	JFD Limited
Position	Senior QC Inspector
General Phone	01224 740 145
Opera Account	VST036
Date Received	06/Apr/2021
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	End Of Life
SRN33606	8010050	102093	Oxygen Sensor VST	Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Return Unrepaired
SRN33607	8010050	102066	Oxygen Sensor VST	Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	End Of Life
SRN33608	8010050	102148	Oxygen Sensor VST	Time :0 Hour(s)

Sensor reported as failed mag range testing, this is outside of the scope of warranty.

Sensor dismantled, unable to ascertain reason for raised mag signature in the wiring. Could have been caused during manufacture or at JFD, there was a delay in JFD reporting the problem.

Repair	Ref	S/N	Equipment Type	Return Unrepaired
SRN33975	8010050	101971	Oxygen Sensor VST	Time :0 Hour(s)

Repair	Ref	S/N	Equipment Type	Return Unrepaired
SRN33976	8010050	101964	Oxygen Sensor VST	Time :0 Hour(s)