

Service Repair Sheet 67886

Contact Name	Autumn Briggs
Company/ Hospital Name	Sheffield Childrens Hospital NHS Trust
Department	Procurement Department
Position	Buyer
Direct Phone	0114 2269856
General Phone	01142 71 7000
Opera Account	00004580
Email	sth.schteam@nhs.net
Date Received	08/Jul/2021
Booked in By	Catherine Spence

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33986	0110705	100053	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110705 Oxygen sensor MLF-19

The MLF-19 Oxygen sensor has been replaced under warranty with SN:100068.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33987	0110705	100055	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110705 Oxygen sensor MLF-19

The MLF-19 Oxygen sensor has been replaced under warranty with SN:100069.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33988	0110705	100057	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110705 Oxygen sensor MLF-19

The MLF-19 Oxygen sensor has been replaced under warranty with SN:100070.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN33989	0110705	100058	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110705 Oxygen sensor MLF-19

The MLF-19 Oxygen sensor has been replaced under warranty with SN:100071.

