

Service Repair Sheet SRS67879

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Jaspal Saimbi

Company/ Hospital Name

Worthing Hospital

Department

Medical Electronics

Position

Technician

Direct Phone

ext 85268

General Phone

01903 20 51 11

Opera Account

00004621

Email

jaspal.saimbi@nhs.net

Order Number

Date Received

01/Jul/2021

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Quote

Notes 29/Jun/2021 Steve Hardaker

29/Jun/2021 Steve Hardaker

29/Jun/2021 Steve Hardaker

Returning an MX300 out of warranty for repair, s/n 313694. It s reading 00.0, they have tried a new sensor so I suggested it will be the cable but he wanted to send it in anyway.

Advised we can give it a Functional Check Service (pn 0180005) for Â£45.00+VAT plus parts. If it needs more than a cable, please advise him and issue a repair quote.

01/Jul/2021 Robert Connor

Received 1 x MX300 s/n 313694, with base stand, coiled cable s/n 0005689, R17MED s/n 524633, with flow diverter.

Ready For quote

CC, Neen 9-7-2021

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33971	Oxygen Monitor	0111235	313694	222
SRN33972	Oxygen Monitor Cable	0131202	0005689	
SRN33973	Oxygen Sensor	0110017	524633	

0180005 x 1 @ £45

S/N, SRS, SRN

⊙

0131202 x 1 @ £20.

SRS, SRN.