

Service Repair Sheet SRS67899

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Balal Tariq

Company/ Hospital Name

University Hospital Crosshouse

Department

Medical Physics

Position

Technician

Direct Phone

01563 827457

General Phone

01563 21133

Opera Account

00001320

Email

balal.tariq@aapct.scot.nhs.uk

Order Number

Date Received

20/Jul/2021

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Quote

Notes 15/Jul/2021 Steve Hardaker

15/Jul/2021 Steve Hardaker

15/Jul/2021 Steve Hardaker

Returning a physically damaged VM2500-S, s/n 60920171 that he says requires a new display and case. Please assess and quote for repair.

20/Jul/2021 Robert Connor

1 x VM2500S s/n 60920171, front of case and screen punctured

Ready For quote

CGreen 23.7.2021

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34009	Capnograph	4410520	60920171	N

44400000 x 1 = 1/2 hr @ £90 per hr = £45
S/N, SRS, SRN

44000070 x 1 @ £50.30
SRS, SRN

4430120 x 1 £80.00
SRS, SRN

4430607 x 1 £7.35
SRS, SRN

4420598 x 1 £42.95
SRS, SRN

mps x 1 £10

NHS Ayrshire & Arran
University Hospital Crosshouse - Medical Physics Department

**Ayrshire
& Arran**

From:

Mr Balal Tariq
 Clinical Technologist Specialist

Contact:

T: Helpdesk 01563 827456
 T: 01563 826080
 E: Balal.Tariq@aapct.scot.nhs.uk
 E: Clinical_MedicalPhysics_XH@aapct.scot.nhs.uk

Address:

Medical Physics

 University Hospital Crosshouse
 Kilmarnock Road
 Kilmarnock
 Scotland, UK

 KA2 OBE

Job No:	206496	Date	15 July 2021
Equipment No:	23578 - 23579	Site:	Crosshouse
Serial No:	60920171	Location:	ITU
Brand:	Viamed	Contact Telephone:	01563 826080
Model:	VM-2500-S	Contact Name:	Balal Tariq
Category:	Monitor CO2	Purchase Order No:	TBC
Reported Fault:	Smashed screen.		

Return of Equipment or Goods

The Medical Physics Department must be informed of the repair cost; prior to any chargeable work being carried out.

Please turn over for contamination status.

Declaration of Contamination Status

Medical Physics Department, University Hospital Crosshouse, Kilmarnock, KA2 OBE



Version 00.1 (XH)

Date approved 02/10/2018

Author: Morag Ross

Active Users

▼ Search

**Select Currency**Pounds| Euros| Usd**Repair SRS67899 Values in Pounds @ £1: £1.00**

SRN34009	Capnograph	4410520			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		4420598	1	£42.95	£42.95
		4430607	1	£7.35	£7.35
		4430120	1	£72.00	£72.00
		4400070	1	£50.30	£50.30
		4440000	0.5	£90.00	£45.00
				Parts Cost	£217.60

80.00

CHECK PRICES BEFORE SENDING QUOTE

Quote Sent

;