

Service Repair Sheet SRS67873

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Stephen Linton

Company/ Hospital Name

Antrim Area Hospital

Department

Position

Direct Phone

07919575293

General Phone

0289 442 4000

Opera Account

00000128

Email

Order Number

Date Received

20/Jul/2021

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Warranty

Notes 18/Jun/2021 Sophie Lines

18/Jun/2021 Sophie Lines

18/Jun/2021 Sophie Lines

18/Jun/2021 Sophie Lines

Stephen phoned - he sent a matched pair yesterday that had failed. He now has another matched pair that has failed under warranty so set up a new SRS for those - would like to know if there may be a problem with this batch? Will pass contact details to SJH and SN if they would like to discuss. Serial numbers V103518/V103519

20/Jul/2021 Robert Connor

2 x R22Vi s/n V103518, V103519

Ready For quote

Repair Complete Signed

CGNEEN 23.7.2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34010	Oxygen Sensor	0110020	V103518	Yes
SRN34011	Oxygen Sensor	0110020	V103519	Yes

3 pair  
0110072  
split to  
singles  
for repair  
CG 23/7/21

0140013 x 1 @ £0  
old S/N, SRS, SRN

0110072 x 1 @ £0  
New S/N, SRS, SRN

UPS x 1 @ £0

Clinical Engineering  
Antrim Hospital  
Bush Road  
Antrim  
BT41 2RL

Return number SRS 67873

Serial Numbers  
V103518 & V103519

Regards  
Stephen Linton

[Stephen.linton@northerntrust.hscni.net](mailto:Stephen.linton@northerntrust.hscni.net)