

Service Repair Sheet SRS67906

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Joe Butcher

Company/ Hospital Name

METS t/a VETS

Department

Position

Direct Phone

General Phone

01535666030

Opera Account

00013138

Email

joe.butcher@vetsltd.uk

Order Number

Date Received

22/Jul/2021

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Quote

Notes 21/Jul/2021 Kate Griffiths

21/Jul/2021 Kate Griffiths

Joe would like to drop off an oxygen monitor on Thursday 22.7.21. Cathy aware. I will add more details when Joe replies. It has

22/Jul/2021 Kate Griffiths

21/Jul/2021 Kate Griffiths

21/Jul/2021 Kate Griffiths

Joe would like to drop off an oxygen monitor on Thursday 22.7.21. Cathy aware. I will add more details when Joe replies. It has ``stopped working``. UPDATE:

Model is AX300-I, Serial number 287483

22/Jul/2021 Robert Connor

Received 1 x AX300 s/n 287483, 0131201 s/n 5361, R17MED s/n 474556, with flow diverter and blue T

Ready For quote

Connor 28.7.2021

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34013	Oxygen Monitor	0111230	287483	NO
SRN34014	Oxygen Monitor Cable	0131201	5361	NO
SRN34016	Oxygen Sensor	0110017	474556	Yes

0180004 x 1 @ £45  
S/N, SRS, SRN

0121207 x 1 @ £5.  
SRS, SRN

0131201 x 1 @ £30

... x 1 @ £10 or can collect.



### Select Currency

Pounds| Euros| Usd

### Repair SRS67906 Values in Pounds @ £1: £1.00

SRN34013	Oxygen Monitor	0111230			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0180004	1	£0.00	£0.00
		0121207	1	£5.00	£5.00
SRN34014	Oxygen Monitor Cable	0131201			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		0131201	1	£30.00	£30.00
				Parts Cost	£35.00

by 28-7-2021  
 £45.00

### CHECK PRICES BEFORE SENDING QUOTE

Quote Sent