

Service Repair Sheet SRS67874

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Duncan Clark

Company/ Hospital Name

JFD

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

13/Jul/2021

Booked in By

Robert Connor

Main Company

VandagraphST

Type Return

Warranty

Notes 22/Jun/2021 Steve Nixon

22/Jun/2021 Steve Nixon

22/Jun/2021 Steve Nixon

Unstable high output. Test to see if could be caused by a bubble. Discuss with SN.

13/Jul/2021 Robert Connor

1 x JFD sensor s/n 102258, with truncated wires

16/Jul/2021 Catherine Spence

requested on box 803

22/Jul/2021 Catherine Spence

returned back to supplier

02/Aug/2021 Catherine Spence

Credit received from supplier

02/Aug/2021 Catherine Spence

Failed as signal out of tolerance

02/Aug/2021 Catherine Spence

Send replacement sensor on next order

Ready For quote

Repair Complete Signed

CGNEON 2-8-2021

---

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34001	Oxygen Sensor VST	8010050	102258	Yes

warranty

Please add FOC replacement  
for 1x 8010050 to next order

cg 2.8.2021