

Service Repair Sheet SRS67918

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Dietmar Wood

Company/ Hospital Name

Glan Clwyd Hospital

Department

Position

Direct Phone

01745534506

General Phone

01745 58 39 10

Opera Account

00000580

Email

Dietmar.Wood@wales.nhs.uk

Order Number

Date Received

09/Aug/2021

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Warranty

Notes 04/Aug/2021 Zoey Teal

04/Aug/2021 Zoey Teal

Customer called to say they are sending 2 x 0110017 back as faulty.

Serial numbers 524654 and 524655.

09/Aug/2021 Robert Connor

Received 2 x R-17MED s/n 524654, 524655

Ready For quote

Repair Complete Signed

CGreen 11-8-2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34037	Oxygen Sensor	0110017	524654	Yes
SRN34038	Oxygen Sensor	0110017	524655	Yes

0140013 x 2 FCC
old S/N's, SRS, SRN

0110017 x 2 FCC
New S/N, SRS, SRN

UPS x 1 FCC.