

EBME Department,
Glan Clwyd Hospital,
Sarn Lane,
Bodelwyddan,
LL18 5UJ

5-8-2021



Returns number: SR567918

Please find enclosed x2 0110017 oxygen sensors R-17MED which are showing they are not connected and with no output.

Please also find the delivery note for these.

Thank you.

Kind regards,

Alicia Brelsford

EBME Admin