

Service Repair Sheet 67908

Contact Name	Kenny Ross
Company/ Hospital Name	Solus Medical Limited
Department	Servicing Support
General Phone	03453058098
Opera Account	00012179
Email	UKinfo@vtherm.com
Date Received	05/Aug/2021
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34033	0110425	FK70799030	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110425 Oxygen sensor MAX-250. With `O` ring.

Replaced under warranty with FK70899187
