

Logistics : store :

SCA  
sth.schteam.nhs.net -email.

Service Repair Sheet SRS67886

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Autumn Briggs

Company/ Hospital Name

Sheffield Childrens Hospital NHS Trust

Department

Procurement Department

Position

Buyer

Direct Phone

0114 2269856

General Phone

01142 71 7000

Opera Account

00004580

Email

sth.schteam@nhs.net

Order Number

Date Received

08/Jul/2021

Booked in By

Catherine Spence

Main Company

Viamed

Type Return

Warranty

0114 2269856

0797 131 5076. Mobile.

Received a MLF-19GE  
Sensor as well.  
Spoken to Steve H.

Notes 06/Jul/2021 Steve Hardaker

06/Jul/2021 Steve Hardaker

06/Jul/2021 Steve Hardaker

We have recently discovered that a small production batch of 10 x p/n 0110705 MLF-19 Oxygen Sensors may have been manufactured with the wrong connector.

We have identified that Sheffield Childrens Hospital took delivery of 7 of these sensors over 2 purchase orders, and there is a high probability that these 7 sensors are also incorrect: s/nos 100052-58.

Asked that they return them for immediate replacement under warranty.

07/Jul/2021 Steve Hardaker

06/Jul/2021 Steve Hardaker

06/Jul/2021 Steve Hardaker

06/Jul/2021 Steve Hardaker

We have recently discovered that a small production batch of 10 x p/n 0110705 MLF-19 Oxygen Sensors may have been manufactured with the wrong connector.

We have identified that Sheffield Childrens Hospital took delivery of 7 of these sensors over 2 purchase orders, and there is a high probability that these 7 sensors are also incorrect: s/nos 100052-58.

Asked that they return them for immediate replacement under warranty.

Update - they have only located 4 so far, 100053, 55, 57, 58 and are returning them ASAP.

12/Jul/2021 Robert Connor

Received 5 x MLF-19 s/n 10053, 10055, 10057, 10058.

Also 1 x MLF-19GE s/n 0206382 sent in error, this is not a sensor type sold by us.

Autumn  
on leave  
until 19th  
July 2021  
CG 14<sup>th</sup> 2021

Ready For quote

Repair Complete Signed

CC Neen 13.8.2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33986	Oxygen Sensor	0110705	100053	Yes
SRN33987	Oxygen Sensor	0110705	100055	Yes
SRN33988	Oxygen Sensor	0110705	100057	Yes
SRN33989	Oxygen Sensor	0110705	100058	Yes
SRN33995	Oxygen Sensor		0206382	N

0140010 x 1 FOC

S/N, SRS, SRN - Returning as sent to us by Mistake

UPS x 1 FOC