

Viamed Limited · 15 Station Road · Cross Hills
Keighley · West Yorkshire · BD20 7DT · United Kingdom
Tel: +44 (0)1535 634542/636757 Fax: +44 (0)1535 635582
Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 67916

Contact Name

Company/ Hospital Name

Direct Phone General Phone

Opera Account

Email Order Number

Date Received Booked in By

Swadhipriya Moorthy

Whipps Cross University Hospital

02085356927

Medical Engineering

00003450

swadhi.priya@nhs.net

40690519 17/Aug/2021 Robert Connor

Repair

Ref

S/N

Equipment Type

SRN34088 141

1410000 PR01202A17

Foetal Simulator

Complete - Repaired

Time: 0 Hour(s)

Parts Replaced

Qty: 1

1480000

Foetal Heart Simulator V1000 - Service

Qty: 1 1430309

V1000 Transducer interface cushion.

V1000 has had transducer interface cushion replaced and calibration has been checked