

Service Repair Sheet 67923

Contact Name	Oskar Slechta
Company/ Hospital Name	Chromservis s.r.o
Position	Senior Internal Sales Advisor
Direct Phone	420 274 021 221
Opera Account	00012607
Email	o.slechta@chromservis.eu
Date Received	17/Aug/2021
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34082	0110022	597205	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110022 Oxygen sensor R-22MED

Replaced under warranty with S/N 561016
