Service Repair Sheet SRS67920

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Lisa Vickers

Company/ Hospital Name

Medivent Ltd (Euro)

Department Position

0162 80338

Direct Phone

00353 16280338

General Phone

Opera Account

00007374

Email

info@medivent.ie

Order Number Date Received

12/Aug/2021

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Repair Warranty

Notes 09/Aug/2021 Ryan Swaine

09/Aug/2021 Ryan Swaine 09/Aug/2021 Ryan Swaine

VM-2500-S - SN:A1809150030: Previously sent in under SRS67818. Unit repaired in May 2021, but has since started with the same problem again: "The screen is black and you can hear the pump running for around 20 secs and hear 2 beeps every 10 sec"

12/Aug/2021 Robert Connor

Received 1 x VM-2500-S s/n A1809150030, with battery and silicone cover

Ready For quote

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Wa unty
SRN34073	Capnograph	4410520	A1809150030	10 Y

4440000 × 1 0 €0

Viamed CROSS HILLS KEIGHLEY WEST YORKSHIRE BD20 7DT Unit 10 Hills Industrial Centre, Lucan, Co. Dublin Tel: 01-628 0338 E-mail:info@medivent.ie

DELIVERY/ SHIPPING NOTE

Returns Numbe SRS67920

DATE: 9th August 2021

 DESCRIPTION	QUANTITY	CODE	ORDER NO.
RETURN for Evaluation/Repair			
 VM-2500-S - S/N: A1809150030	1		
Capnograph			
<u> </u>			
*			
		1+1	
Capnograph	1	345	

RECEIVED BY:	
--------------	--

Service Repair Sheet 67920

Contact Name

Company/ Hospital Name

Direct Phone

General Phone

Opera Account

Email

Date Received

Booked in By

Lisa Vickers

Medivent Ltd (Euro)

0162 80338

00353 16280338

00007374

info@medivent.ie

12/Aug/2021

Robert Connor

Repair SRN34073 4410520 A1809150030

Ref

S/N

Equipment Type

Capnograph

Complete - Repaired

Time:0 Hour(s)

The Capnograph VM 2500-S has been repaired. The OLED connector has been fixed in place.