

Service Repair Sheet 67931

Contact Name	Sarah Johnston
Company/ Hospital Name	SMC Ltd
Direct Phone	02890 410136
General Phone	0289 0410136
Opera Account	00012907
Email	<a href="mailto:sjohnston@brennanconi.com">sjohnston@brennanconi.com</a>
Date Received	23/Aug/2021
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	Calibrated
SRN34091	0111263	FA75699022	Oxygen Monitor	Time :0 Hour(s)

The MAXO2ME Oxygen monitor has been tested. The unit is working as expected. A calibration test has been performed on the unit and certificate has been produced.

---