

DESPATCH NOTE: S14906
DATED: 18/08/221
YOUR REF: 180021
OUR REF: SD1018

CONTACT DETAILS: TEL: 01535 634542

A/C NO: VIAM11

RYAN SWAINE
VIAMED LTD
15 STATION ROAD
CROSS HILLS
KEIGHLEY
WEST YORKSHIRE, BD20 7DT

ITEM	PRODUCT CODE	PRODUCT DESCRIPTION	UNIT	LOCATION	ORDERED	DESPATCHED	CALL NO
1	FA75699022	MAXO 2 ME OXYGEN MONITOR	1			1	

PLEASE CALIBRATE AND RETURN
TO BRENNAN & CO NI ASAP.

RETURNS REFERENCE SRS67931

JP 18/8/21

DESPATCH NOTE: S14906
DATED: 18/08/221
YOUR REF: 180021
OUR REF: SD1018

CONTACT DETAILS: TEL: 01535 634542

A/C NO: VIAM11

RYAN SWAINE
VIAMED LTD
15 STATION ROAD
CROSS HILLS
KEIGHLEY
WEST YORKSHIRE, BD20 7DT

ITEM	PRODUCT CODE	PRODUCT DESCRIPTION	UNIT	LOCATION	ORDERED	DESPATCHED	CALL NO
1	FA75699022	MAXO 2 ME OXYGEN MONITOR	1			1	

PLEASE CALIBRATE AND RETURN
TO BRENNAN & CO NI ASAP.

RETURNS REFERENCE SRS67931

JP 18/8/21

Service Repair Sheet 67931

Contact Name	Sarah Johnston
Company/ Hospital Name	SMC Ltd
Direct Phone	02890 410136
General Phone	0289 0410136
Opera Account	00012907
Email	sjohnston@brennanconi.com
Date Received	23/Aug/2021
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Calibrated
SRN34091	0111263	FA75699022	Oxygen Monitor	Time :0 Hour(s)

The MAXO2ME Oxygen monitor has been tested. The unit is working as expected. A calibration test has been performed on the unit and certificate has been produced.
