

Service Repair Sheet SRS67937

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Lisa Vickers

Company/ Hospital Name

Medivent Ltd (Euro)

Department

Position

Direct Phone

General Phone

00353 16280338

Opera Account

00007374

Email

office@medivent.ie

Order Number

Date Received

26/Aug/2021

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Quote

Notes 24/Aug/2021 Ryan Swaine

24/Aug/2021 Ryan Swaine

24/Aug/2021 Ryan Swaine

VM-2500-S â€" S/N: A1809150028 â€" Screen is cracked

26/Aug/2021 Robert Connor

Received 1 x capnograph s/n A1809150028, with li-poly battery and silicone cover, unit has cracked screen.

Ready For quote

CGNEON 31.8.2021

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34100	Capnograph	4410520	A1809150028	N

DIST

4440000 x 0.50 @ €70.00 per hr.
S/N, SRS, SRN.

4430120 x 1 @ 73.00 €
SRS, SRN

UPS x 1
32x24x12cm @ 0.60kg




Unit 10 Hills Industrial Centre, Lucan, Co. Dublin
Tel: 01-628 0338 E-mail: info@medivent.ie

DELIVERY/ SHIPPING NOTE

DATE: 24th August 2021

RECEIVED BY: _____



Select Currency

Pounds| Euros | Usd

Repair SRS67937 Values in Euros @ €1.16000: €1.00

SRN34100	Capnograph	4410520			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		4430120	1	€83.52	€83.52
		4440000	0.5	€104.40	€52.20
				Parts Cost	€135.72

CHECK PRICES BEFORE SENDING QUOTE

Quote Sent

€ Dist

73.00

70.00 per hr

*Cg
31.8.202
as per
intranet*