

## Service Repair Sheet 67922

Contact Name	Phuong Trinh
Company/ Hospital Name	An An Import Export Co Ltd
Direct Phone	+84 987 546 072
Opera Account	CID15101
Email	phukienthaythe@gmail.com
Date Received	12/Aug/2021
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34067	0110429	FH90199212	Oxygen Sensor	

Time :0 Hour(s)

## Parts Replaced

Qty: 1    0110429    Oxygen sensor MAX-250E

This sensor is nonlinear and replaced under warranty with S/N GG35299001

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34068	0110429	FJ12499066	Oxygen Sensor	

Time :0 Hour(s)

## Parts Replaced

Qty: 1    0110429    Oxygen sensor MAX-250E

This sensor is nonlinear and replaced under warranty with S/N GG35299002

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34069	0110429	FJ77299208	Oxygen Sensor	

Time :0 Hour(s)

## Parts Replaced

Qty: 1    0110429    Oxygen sensor MAX-250E

This sensor is nonlinear and replaced under warranty with S/N GG35299003

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34070	0110429	FJ77299212	Oxygen Sensor	

Time :0 Hour(s)

## Parts Replaced

Qty: 1    0110429    Oxygen sensor MAX-250E

This sensor is nonlinear and replaced under warranty with S/N GG35299004

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34071	0110429	GB52899043	Oxygen Sensor	

Time :0 Hour(s)

## Parts Replaced

Qty: 1    0110429    Oxygen sensor MAX-250E

This sensor is low output and replaced under warranty with S/N GG35299005

Service Repair Sheet 67922

Contact Name	Phuong Trinh
Company/ Hospital Name	An An Import Export Co Ltd
Direct Phone	+84 987 546 072
Opera Account	CID15101
Email	phukienthaythe@gmail.com
Date Received	12/Aug/2021
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34072	0110429	GB52899054	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110429    Oxygen sensor MAX-250E

This sensor is nonlinear and replaced under warranty with S/N GG35299006

---