

Service Repair Sheet 67930
Contact Name Magnus Persson
Company/ Hospital Name Swevet - AB
Direct Phone 46 416 258 21
General Phone 46 771215500
Opera Account 00006308
Email magnus.persson@swevet.se
Date Received 01/Sep/2021
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN34103	0111263	FC07299007	Oxygen Monitor	Complete - Repaired Time :0 Hour(s)

Parts Replaced
Qty: 1 0131700 MaxO2 ME Sensor Cable.

Replaced faulty sensor cable.

Repair	Ref	S/N	Equipment Type	
SRN34104	0111263	FC07299009	Oxygen Monitor	Complete - Repaired Time :0 Hour(s)

Parts Replaced
Qty: 1 0131700 MaxO2 ME Sensor Cable.
Qty: 1 9950054 Batteries 1.5V AA. 2700 mAh.

Replaced faulty sensor cable and batteries.

Repair	Ref	S/N	Equipment Type	
SRN34105	0110452	FC24599068	Oxygen Sensor	No Fault Found Time :0 Hour(s)

This sensor is no fault found.

Repair	Ref	S/N	Equipment Type	
SRN34106	0110452	FC24599058	Oxygen Sensor	No Fault Found Time :0 Hour(s)

This sensor is no fault found.
