

Service Repair Sheet SRS67937

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Lisa Vickers

Medivent Ltd (Euro)

00353 16280338

00007374

office@medivent.ie

26/Aug/2021

Robert Connor

Viamed

Quote

Notes 24/Aug/2021 Ryan Swaine

24/Aug/2021 Ryan Swaine

24/Aug/2021 Ryan Swaine

VM-2500-S â€" S/N: A1809150028 â€" Screen is cracked

26/Aug/2021 Robert Connor

Received 1 x capnograph s/n A1809150028, with li-poly battery and silicone cover, unit has cracked screen.

Ready For quote

CCNeen 31.8.2021

Repair Complete Signed

CCNeen 8.9.2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34100	Capnograph	4410520	A1809150028	N

DIST

4440000 x 0.50 @ €70.00 per hr.  
S/N, SRS, SRN.

4430120 x 1 @ 73.00 €  
SRS, SRN

UPS x 1  
32x24x12cm @ 0.60kg



Service Repair Sheet 67937

Contact Name	Lisa Vickers
Company/ Hospital Name	Medivent Ltd (Euro)
General Phone	00353 16280338
Opera Account	00007374
Email	<a href="mailto:office@medivent.ie">office@medivent.ie</a>
Order Number	7282
Date Received	26/Aug/2021
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	
SRN34100	4410520	A1809150028	Capnograph	Complete - Repaired Time :0.5 Hour(s)

Parts Replaced

Qty: 1	4430120	OLED Display
Qty: 0.5	4440000	Labour - VM-2500 Capnograph

The Capnograph VM 2500-S has been repaired. The OLED display has been replaced.

---