

Service Repair Sheet SRS67925

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Sudath Weeraman

Prime Lanka Associates

94718732285

00006714

sudathweeraman17@gmail.com

20/Sep/2021

Robert Connor

Viamed

Warranty

Notes 12/Aug/2021 Kate Griffiths

12/Aug/2021 Kate Griffiths

GC80699061 MAX-250E Oxygen sensor "is defective", to return under warranty.

20/Sep/2021 Robert Connor

Received 1 x MAX250E s/n GC80699063

Ready For quote

Repair Complete Signed

Cgreen 21.9.2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34201	Oxygen Sensor	0110429	GC80699061	Yes

0140013 x 1 fOC
Old S/N, SRS, SRN

0110429 x 1 fOC
New S/N, SRS, SRN

ExW. (usually Sky Cargo) - Ship with next order @ 21.9.2021



"Bringing quality to life."

No: 57/8, P.B. Alwis Perera Mawatha, Katubedda,
Moratuwa, Sri Lanka.

+94 071 873 2285 / +94 011 345 9456

011 262 4324

primelanka07@gmail.com
sudathweeraman17@gmail.com

06 September 2021

The Repair Team.

Viamed LTD, No.15, Station Road, Cross Hills, Keighley
West Yorkshire, BD20 7DT
United Kingdom.

Dear Sir,

This is warranty replacement notice, for Oxygen sensor model MAX-250E & R-24MED
Please note below details for your reference.

Model – Oxygen Sensor MAX-250E – S/N GC80699061

Return Reference No. SRS-67925

Commercial Invoice No. RVM131278-1 (05-07-2021)

Model – Oxygen Sensor R-24MED – S/N609211

Return Reference No. SRS-67936

Commercial Invoice No. RVM130823 (17-06-2021)

Thank you,

You're faithfully

PRIME LANKA ASSOCIATES

S.J. Weeraman

Proprietor
Prime Lanka Associates

No.57/8, P.B.Alwis Perera Mawatha
Katubadda, Moratuwa
Sri Lanka.