

Service Repair Sheet 67925

Contact Name	Sudath Weeraman
Company/ Hospital Name	Prime Lanka Associates
Direct Phone	94718732285
Opera Account	00006714
Email	sudathweeraman17@gmail.com
Date Received	20/Sep/2021
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34201	0110429	GC80699061	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110429 Oxygen sensor MAX-250E

Replaced under warranty with S/N GG35299040
