

Service Repair Sheet SRS67936

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600
Sudath Weeraman
Prime Lanka

9410718732285

00006714

sudathweeraman17@gmail.com

20/Sep/2021

Robert Connor

Viamed

Warranty

Notes 23/Aug/2021 Sarah Walton

23/Aug/2021 Sarah Walton

From Customer - 1 x R-24MED oxygen sensor is defective, this is purchased 17th June 2021,
Serial no. 609211 (unable to increase oxygen percentage,maximund 30%)

Invoice : RVM130823-1

20/Sep/2021 Robert Connor

Received 1 x R24MED s/n 609211

Ready For quote

Repair Complete Signed

CGNEON 21-9-2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34202	Oxygen Sensor	0110024	609211	Yes

0140013 x 1 FOC
old S/N, SRS, SRN

0110024 x 1 FOC
New S/N, SRS, SRN

Exw (sky cargo)-I think. Ship with next order.



"Bringing quality to life."

No: 57/8, P.B. Alwis Perera Mawatha, Katubedda,
Moratuwa, Sri Lanka.

+94 071 873 2285 / +94 011 345 9456

011 262 4324

primelanka07@gmail.com
sudathweeraman17@gmail.com

06 September 2021

The Repair Team.

Viamed LTD, No.15, Station Road, Cross Hills, Keighley
West Yorkshire, BD20 7DT
United Kingdom.

Dear Sir,

This is warranty replacement notice, for Oxygen sensor model MAX-250E & R-24MED
Please note below details for your reference.

Model – Oxygen Sensor MAX-250E – S/N GC80699061

Return Reference No. SRS-67925

Commercial Invoice No. RVM131278-1 (05-07-2021)

Model – Oxygen Sensor R-24MED – S/N609211

Return Reference No. SRS-67936

Commercial Invoice No. RVM130823 (17-06-2021)

Thank you,

You're faithfully

PRIME LANKA ASSOCIATES


S.J. Weeraman

Proprietor
Prime Lanka Associates

No.57/8, P.B. Alwis Perera Mawatha
Katubadda, Moratuwa
Sri Lanka.