

618719

Service Repair Sheet SRS67954

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Oskar Slechta

Company/ Hospital Name

Chromservis s.r.o

Department

Position

420274021221

Direct Phone

General Phone

Opera Account

00012607

Email

o.slechta@chromservis.eu

Order Number

Date Received

21/Sep/2021

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Warranty

Notes 16/Sep/2021 Zoey Teal

16/Sep/2021 Zoey Teal

Sending in a faulty R-22MED sensor. The reading is 2% only on air 21%. It is not possible to calibrate it.

21/Sep/2021 Robert Connor

Received 1 x R22MED s/n 597204

Ready For quote

Repair Complete Signed

CGNEEN 24-9-2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34208	Oxygen Sensor	0110022	597204	Yes

0140013 x 1 FOC
old S/N, SRS, SRN

0110022 x 1 FOC
New S/N, SRS, SRN

UPS x 1 FOC

Ref: SRS67954

**To attn. Zoey Teal
Viamed Ltd.**

Prague, September 20th., 2021

Dear Zoey,

after our E-mailing, we are sending you to back **1x R-22MED sensor, s/n 597204-B1**.
The reading is 2% only on air (21%), it isn't possible to calibrate it. I would like to ask you
for replacement under warranty, if it is possible.

Thanks so much,
best regards


Oskar Slechta
Chromservis Czech