

Service Repair Sheet 67960

Contact Name	Philip Tan
Company/ Hospital Name	Junnimed
Direct Phone	+65 65467737
Opera Account	00007983
Email	philip_tan@junnimed.com
Date Received	30/Sep/2021
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34212	0110017	605930	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110017    Oxygen sensor R-17MED

Replaced under warranty with S/N 617320

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34213	0110017	617208	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110017    Oxygen sensor R-17MED

Replaced under warranty with S/N 617321