on quote
02/Sep/2021 Catherine Spence
still on quote
07/Sep/2021 Catherine Spence
chased quote with mike over the pho

chased quote with mike over the phone, he will try and contact his customer to see if they still want to go ahead with it 08/Sep/2021 Catherine Spence

email received from Mike last night to say that customer no longer requires this unit, please dispose of it

08/Sep/2021 Catherine Spence

received a second email to request that we return the unit back to Thames as un-repaired

08/Sep/2021 Catherine Spence

will contact Bluepoint today and ask for them to return the unit

08/Sep/2021 Catherine Spence email sent to bluepoint to request item to be returned 09/Sep/2021 Catherine Spence Cancel QVM131705

09/Sep/2021 Derek Lamb unit disposed of Derek Lamb Return Items to Stock. 04/Oct/2021 Catherine Spence to send back to customer as not repaired as requested

Ready For quote

Repair Complete Signed

CGNEON 5-10-2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN33689	Capnograph	4410540	A1610160014	2
SRN33688	Pulse Oximetery Ear Clip Sensor	0015000	ESKB01690	Yes

0140050 × 1 FOC SIN, SRS, SRN Returned unrepowred as requested.

0040001 × 1 FOC SIN, SRS, SRN

UPS × 1 FOC.

## names Medical Ltd

8 A'Becket Gardens

Worthing, West Sussex BN13 2BW

www.thamesmedical.com

info@thamesmedical.com email

01903 522911 tel

01903 522922

Experts in patient monitoring and anaesthesia

Thames Medical

## **PURCHASE ORDER**

order#

PO-01550

date

13/05/2021

vendor address Viamed Ltd

15 Station Road Cross Hills

Keighley, West Yorkshire

DESCRIPTION

SN-A1610160014

**BD20 7DT** 

contact

Kate

phone fax

01535 634542

01535 635582

arrier

payment terms

Net 30

**UPS** 

ITEM

QUANTITY UNIT PRICE

SUB-TOTAL

£0.00

RL2WR

TML-V-VM2500S3- VM2500S - Warranty Repair - Warranty Repair of

Service Level 2

VM2500S

PRODUCT CODE

Sidestream Capnograph

**VENDOR** 

remarks

SRS 67833

SUB-TOTAL

£0.00

£0.00 £0.00

TOTAL

TAX

£0.00