Service Repair Sheet SRS67934

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Dennis Vessey

Megalodon

25/Aug/2021 Robert Connor VandagraphST Warranty

Notes 19/Aug/2021 Steve Nixon 19/Aug/2021 Steve Nixon 19/Aug/2021 Steve Nixon

Returning 1 x 8010012
25/Aug/2021 Robert Connor
Received 1 x SC-I22D s/n ISC116012
25/Aug/2021 Robert Connor
Cell scanned to RMA box 809
02/Sep/2021 Catherine Spence
rma received due to be sent to supplier
06/Sep/2021 Catherine Spence
sent back on RMA300242847
13/Sep/2021 Catherine Spence
with supplier
20/Sep/2021 Catherine Spence
Credit received from supplier for this sensor
27/Sep/2021 Catherine Spence
details sent to steve nixon

Ready For quote

Repair Complete Signed

CGreen 5-10-2021

| SRN | Equipment | Stock Ref | Serial Number | Warranty |
|----------|-------------------|-----------|---------------|----------|
| SRN34092 | Oxygen Sensor VST | 8010012 | ISC116012 | Yes |

Prease replace 1x 8010012 FOC on next order cg 5-10-2021