

Viamed Limited · 15 Station Road · Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634542/636757 Fax: +44 (0)1535 635582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 67968

Contact Name

Company/ Hospital Name

Position **Direct Phone** General Phone Opera Account

Email

Date Received Booked in By

David Mauron

Nufer Medical (USD A/C)

Service Technician +4131 958 66 66 0041 31 9586666

00007786

d.mauron@nufer-medical.ch

12/Oct/2021 Robert Connor

Repair SRN34229 0110039 V100936

S/N

Equipment Type

Oxygen Sensor

Under Warranty

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110039

Oxygen sensor R-22VA.

Replaced under warranty with S/N V101238