

Service Repair Sheet SRS67984

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Amanda Richardson

Company/ Hospital Name

Medivent Ltd (Euro)

Department

Position

Direct Phone

0035316280338

General Phone

00353 16280338

Opera Account

00007374

Email

office@medivent.ie

Order Number

Date Received

04/Nov/2021

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Quote

Notes 19/Oct/2021 Zoey Teal

19/Oct/2021 Zoey Teal

Sending in a faulty MX300. They have tried a new cable and sensor but it will only works sometimes and then switches off. Serial number 329809.

28/Oct/2021 Zoey Teal

Also sending back 2 x 0110017 as faulty. Serial numbers 617218 and 617474.

04/Nov/2021 Robert Connor

Received 1 x MX300 s/n 329809, with coiled cable s/n 0010709, and 3 x AA battery. 2 x R-17MED s/n 134695, 566049

Ready For quote

CC. NEON 12.11.2021

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34324	Oxygen Monitor	0111235	329809	2
SRN34325	Oxygen Monitor Cable	0131202	0010709	2
SRN34326	Oxygen Sensor	0110017	134695	2
SRN34327	Oxygen Sensor	0110017	566049	Yes

0180005 x 1 €37.75
S/N, SRS, SRN

→ SRN 34324.

0140012 x 1
old S/N, SRS, SRN

— SRN 34326

0110017 x 1 €32.00
NEW S/N, SRS, SRN
S/N

UPS x 1 32x26x12cm 1kg.