

Service Repair Sheet SRS67996

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Alicia Brelsford

Glan Clwyd Hospital

EBME Administration

01745534506

00000580

Alicia.Brelsford@wales.nhs.uk

16/Nov/2021

Robert Connor

Viamed

Warranty

Notes 10/Nov/2021 Kate Griffiths

10/Nov/2021 Kate Griffiths

Cusatomer says

10/Nov/2021 Kate Griffiths

Update - "The sensor is reading as though it has an open sensor"

16/Nov/2021 Robert Connor

Received 1 x R17MED s/n 606017

Ready For quote

Repair Complete Signed

CCNEEN 18.11.21

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34339	Oxygen Sensor	0110017	606017	Yes

0140013 x 1 FOC
old SIN's, SRS, SRN

0110017 x 1 FOC
new SIN, SRS, SRN

UPS x 1 FOC.

EBME Department,
Glan Clwyd Hospital,
Sarn Lane,
Bodelwyddan,
LL18 5UJ

10/11/2021

Please find our 0110017 oxygen sensor R-17MED SN: 606017 which is reading as though it has an open sensor. Thank you.

Kind regards,

Alicia Brelsford

EBME Admin

01745 534506