

Service Repair Sheet 67996

Contact Name	Alicia Brelsford
Company/ Hospital Name	Glan Clwyd Hospital
Department	EBME Administration
Direct Phone	01745534506
Opera Account	00000580
Email	Alicia.Brelsford@wales.nhs.uk
Date Received	16/Nov/2021
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34339	0110017	606017	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110017 Oxygen sensor R-17MED

Replaced under warranty with S/N 646410
