

Service Repair Sheet SRS67988

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Sudath Weeraman

Company/ Hospital Name

Prime Lanka

Department

Position

Direct Phone

General Phone

9410718732285

Opera Account

00006714

Email

sudathweeraman17@gmail.com

Order Number

Date Received

22/Nov/2021

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Warranty

Notes 29/Oct/2021 Sarah Walton

29/Oct/2021 Sarah Walton

Two faulty MAX-250E sensors

Serial No: GG35299017 / GG63299007

22/Nov/2021 Robert Connor

Received 2 x MAX-250E s/n GG35299017, GG63299007, parcel tampered with by DHL.

Ready For quote

Repair Complete Signed

CGreen 24-11-2021

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34344	Oxygen Sensor	0110429	GG35299017	Yes
SRN34345	Oxygen Sensor	0110429	GG63299007	Yes

0140013 x 2
old S/N, SRS, SRN

0110429 x 2
New S/N, SRS, SRN

Exw. -> ship with next Order.



"Bringing quality to life."

No: 57/8, P.B. Alwis Perera Mawatha, Katubedda,
Moratuwa, Sri Lanka.

+94 071 873 2285 / +94 011 345 9456

011 262 4324

primelanka07@gmail.com
sudathweeraman17@gmail.com

10 November 2021

The Repair Team.
Viamed LTD, No.15, Station Road, Cross Hills, Keighley
West Yorkshire, BD20 7DT
United Kingdom.

Dear Sir,

The warranty replacement notice, for Oxygen sensor model MAX-250E
Please note below details for your reference.

Model – Oxygen Sensor MAX-250E

1. S/N - GG35299017
2. S/N - GG63299007

Return Reference No. SRS-67988

Thank you,

You're faithfully

S.J. Weeraman

Prime Lanka Associates
No.57/8, P.B. Alwis Perera Mawatha
Katubadda, Moratuwa
Sri Lanka.