

Viamed Limited · 15 Station Road · Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634542/636757 Fax: +44 (0)1535 635582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 67988

Contact Name

Company/ Hospital Name

General Phone Opera Account

Email

Date Received Booked in By

Sudath Weeraman

Prime Lanka 9410718732285

00006714

sudathweeraman17@gmail.com

22/Nov/2021

Robert Connor

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34344

0110429 GG35299017

Oxygen Sensor

Time: 0 Hour(s)

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110429

Oxygen sensor MAX-250E

Replaced under warranty with S/N GC63299084

Repair

Ref

S/N 0110429 GG63299007 **Equipment Type**

Oxygen Sensor

Under Warranty

Parts Replaced

SRN34345

Qty: 1

0110429

Oxygen sensor MAX-250E

Replaced under warranty with S/N GC63299085