Service Repair Sheet SRS67999       Date Promised to Return: 01 Jan 1970 -3600

| | |
|---|---|
| Contact Name | Philip Tan |
| Company/ Hospital Name | Junnimed Services Pte Ltd |
| Department | |
| Position | |
| Direct Phone | 6565467737 |
| General Phone | 0065 6546 7737 |
| Opera Account | 00007983 |
| Email | philip_tan@junnimed.com |
| Order Number | |
| Date Received | 22/Nov/2021 |
| Booked in By | Robert Connor |
| Main Company | Viamed |
| Type Return | Warranty |

Notes 11/Nov/2021 Sarah Walton
11/Nov/2021 Sarah Walton
Serial No. 617216
Faulty sensor to be returned.
I have asked the customer if they are using with an AX or MX unit and if so can they check the cable first
12/Nov/2021 Sarah Walton
Customer has tried using a different sensor with the cable and it works etc so returning the faulty sensor
22/Nov/2021 Robert Connor
Received 1 x R17MED s/n 617216, with flow diverter.


Ready For quote          _____

Repair Complete Signed      *CGreen   24-11-2021*

| SRN | Equipment | Stock Ref | Serial Number | Warranty |
|---|---|---|---|---|
| SRN34343 | Oxygen Sensor | 0110017 | 617216 | Yes |

*0140013 x 1*
*old S/N, SRS, SRN*

*0110017 x 1*
*New S/N, SRS, SRN*

*UPS x 1*
*23x15x12cm 0.20kg*
*or wait to see if they*
*are placing an order for. cg 24-11-21*

## PROFORMA INVOICE

**SENDER**

Philip Tan/ Lilian Lee
JUNNIMED SERVICES PTE LTD
15 CHANGI NORTH STREET 1
#01-20
I-LOFTS @ CHANGI
SINGAPORE 498765

**RECIPIENT**

Sarah Walton
Viamed Limited
15 Station Road - Cross Hills
Keighley - West Yorkshire
BD20 7DT, UK

DATE: 15 November 2021

| Quantity | Description | Unit Price (USD) | Total Price (USD) |
|---|---|---|---|
| 1 unit | Faulty Sensor (SN No:617321) | $5.00 | $5.00 |

# Return Reference Number: SRS67999.

COO: UK

Shipment of no commercial value
Value for custom purposes only

‾‾‾‾‾‾‾‾‾‾‾‾‾‾‾‾‾‾‾‾‾‾‾‾
Authorised Signature