

Service Repair Sheet 67999

Contact Name	Philip Tan
Company/ Hospital Name	Junnimed Services Pte Ltd
Direct Phone	6565467737
General Phone	0065 6546 7737
Opera Account	00007983
Email	<a href="mailto:philip_tan@junnimed.com">philip_tan@junnimed.com</a>
Date Received	22/Nov/2021
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34343	0110017	617216	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110017    Oxygen sensor R-17MED

Replaced under warranty with S/N 674219