

Viamed Limited · 15 Station Road · Cross Hills Keighley · West Yorkshire · BD20 7DT · United Kingdom Tel: +44 (0)1535 634542/636757 Fax: +44 (0)1535 635582 Email: info@viamed.co.uk Website: www.viamed.co.uk

Service Repair Sheet 68028

Contact Name

Company/ Hospital Name

Department **Direct Phone** General Phone

Opera Account

Email

**Date Received** Booked in By

Derek Nairns

Kettering General Hospital

Medical Electronics

01536492269

01536 492000

00002380

d.nairms@nhs.net

20/Dec/2021

Robert Connor

Repair SRN34489

S/N 0110043 V108087 **Equipment Type** 

Oxygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1

0110043

Oxygen sensor R-43V. Pack of 2 sensors.

Replaced under warranty with S/N V108208/V108101

Repair SRN34490 Ref

S/N 0110043 V108099 **Equipment Type** 

Oxygen Sensor

**Under Warranty** 

**Under Warranty** 

Time: 0 Hour(s)

Replaced under warranty with S/N V108208/V108101