Service Repair Sheet SRS68033

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Arlene Gallagher

Forth Valley Royal Hospital

Medical Physics Dept

Ms Gallagher

01324 566953

00004880

arlene.gallagher@nhs.scot

20/Dec/2021

Robert Connor

Viamed

Quote

Notes 20/Dec/2021 Robert Connor 20/Dec/2021 Robert Connor 1 x V1000 s/n PR02724A15, with grey silicone cover, battery contacts look misaligned.

Ready For quote

CGNEEN 21-12-2021

Repair Complete Signed

SRN	Equipment Foetal Simulator	Stock Ref	Serial Number	Warranty	
SRN34491		1410000	PR02724A15	N	

14400000 X 0.5 2 E90 = E45 SIN, SRS, SRN

1230310 × 4 20. SRS, SRN

UPS X1 0 £10

To: VIAMED Forth Valley
Medical Physics Department
Forth Valley Royal Hospital
Stirling Road
Larbert
FK5 4WR



Date: Thursday, 16 December 2021

Tel: 01324-566-953

Email: arlene.gallagher@nhs.scot

Dear Sir/Madam,

Please find enclosed the following item for repair/service/calibration.

Item: V1000

Equipment No.: 223735

Serial No.: PR02724A15

Fault: Unit not staying on, even with new batteries fitted.

If the work required is not covered under warranty or by a service contract please email a quote to the above address.

Please provide a service report when the item is returned.

Yours faithfully,

Arlene Gallagher

stockboo x

stock

producti returns sales



meetings opera

## **Select Currency**

1ookup

employee external iso

Pounds Euros Usd

## Repair SRS68033 Values in Pounds @ �1: �1.00

La contraction of the second	Foetal Simulator Parts Required		Quantity	Unit Cost	Total Line
		1440000	0.5	<b>\$</b> 90.00	<b>4</b> 5.00
				Parts Cost	<b>4</b> 5.00

## CHECK PRICES BEFORE SENDING QUOTE

Quote Sent