

Service Repair Sheet 68034
Contact Name Apostolos Atsalakis
Company/ Hospital Name XHALE S.A.
General Phone +30 693 660 9908
Opera Account 00006401
Email apostolos@endomedical.co
Date Received 15/Dec/2021
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34459	0110081	684392	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696668

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34460	0110081	684393	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696669

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34461	0110081	684395	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696670

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34462	0110081	684396	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696671

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34463	0110081	684397	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696672

Service Repair Sheet 68034
Contact Name Apostolos Atsalakis
Company/ Hospital Name XHALE S.A.
General Phone +30 693 660 9908
Opera Account 00006401
Email apostolos@endomedical.co
Date Received 15/Dec/2021
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34464	0110081	684400	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696673

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34465	0110081	684402	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696674

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34466	0110081	684404	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696675

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34467	0110081	684406	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696676

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34468	0110081	684410	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696677

Service Repair Sheet 68034
Contact Name Apostolos Atsalakis
Company/ Hospital Name XHALE S.A.
General Phone +30 693 660 9908
Opera Account 00006401
Email apostolos@endomedical.co
Date Received 15/Dec/2021
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34469	0110081	684411	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696678

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34470	0110081	684412	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696679

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34471	0110081	684414	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696680

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34472	0110081	684415	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696681

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34473	0110081	684416	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696682

Service Repair Sheet 68034
Contact Name Apostolos Atsalakis
Company/ Hospital Name XHALE S.A.
General Phone +30 693 660 9908
Opera Account 00006401
Email apostolos@endomedical.co
Date Received 15/Dec/2021
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34474	0110081	684417	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696683

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34475	0110081	684419	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696684

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34476	0110081	684423	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696685

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34477	0110081	684424	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696686

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34478	0110081	684426	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696687

Service Repair Sheet 68034
Contact Name Apostolos Atsalakis
Company/ Hospital Name XHALE S.A.
General Phone +30 693 660 9908
Opera Account 00006401
Email apostolos@endomedical.co
Date Received 15/Dec/2021
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34479	0110081	684430	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696688

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34480	0110081	684432	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696689

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34481	0110081	684433	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696690

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34482	0110081	684434	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696691

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34483	0110081	684435	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696692

Service Repair Sheet 68034

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	XHALE S.A.
General Phone	+30 693 660 9908
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	15/Dec/2021
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34484	0110081	684436	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696693

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34485	0110081	684437	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696694

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34486	0110081	684440	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 696695
