Service Repair Sheet SRS68022

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

John Tanaka

Benson Medical Industries Inc

VP Sales and Marketing

0019054750401

001 905475-0401

00006089

jtanaka@bensonmedical.ca

15/Dec/2021

Robert Connor

Viamed

Warranty

Notes 02/Dec/2021 Ryan Swaine 02/Dec/2021 Ryan Swaine

1. Warranty repair:

Viamed VM-2500-M, serial no. A1707130009

Invoiced on March 26 2021

Invoice no. RVM129501-1

Problem: Display screen is blotchy and very difficult to read.

2. Request for repair estimate:

Viamed Mainstream Sensor, serial no. 201929 (from one of our demo units).

Problem: will not display (recurring message to

06/Dec/2021 Ryan Swaine

Explained that it is unlikely we can repair Viamed Mainstream Sensor, serial no. 201929, so this part will not be returned.

15/Dec/2021 Robert Connor

Received 1 x VM-2500-M s/n A1707130009, with li-poly battery

Ready For quote

C Green 5-1-2022

Repair Complete Signed

Stock Ref | Serial Number | Warranty Equipment SRN 4410530 A1707130009 Yes NO SRN34387 Capnograph

4440000 × 0.50 @ E90 per hr. SIN, SRS, SRN

4430120 × 1 £66.00

OPS X 1 32x26x12cm 0-80kg



151 Esna Park Drive, Unit# 19 Markham, Ontario, L3R 3B1 Telephone: (905) 475-0401 Toll Free: (800) 563-3859 Toll Free Fax: (888) 900-3131 Web: www.bensonmedical.ca

## **Purchase Order**

Date Page
Dec 08, 2021 Page 1 of 1

Purchase Order Number
63616

Vendor Address:

VIAMED LIMITED 15 STATION ROAD CROSS HILLS KEIGHLEY, WEST YORKSHIRE BD20 7DT UK Ship To:

BENSON MEDICAL INDUSTRIES INC 151 ESNA PARK DRIVE UNIT 19 MARKHAM, ONTARIO L3R 3B1

Reference	Vendor Number	Terms	Ship Via	Expected Arriva
	VIAMED	30DAYS	UPS STANDARD	

Qty. Ordered	Vendor Item Number	Description	Unit Cost	UOM	Extended Price
0		RMA #SRS68022  WARRANTY REPAIR OR REPLACEMENT  1 EACH VM-2500-M VETERINARY MONITOR SERIAL #A1707130009  1 INV #RVM129501-1 INV DATE MAY 6/21 BENSON PO 63190  PROBLEM: DISPLAY IS DISTORTED AND UNREADABLE	0.00	EA	0.00
Comments:			Total Excluding Tax  Total tax  Total purchase orde		0.00
GST # 100474279RT PST # 17405785					0.00



## **Select Currency**

Pounds Euros Usd

## Repair SRS68022 Values in Pounds @ \$1: \$1.00

SRN34387	Capnograph	4410530			
	Parts Required	Reference	Quantity	Unit Cost	Total Line
		4430120	1	<b>♦</b> 72.00	<b>\$</b> 72.00
		4440000	0.5	<b>\$</b> 90.00	<b>4</b> 5.00
				Parts Cost	<b>♦</b> 117.00

## CHECK PRICES BEFORE SENDING QUOTE

Quote Sent