

Service Repair Sheet SRS68004

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Ryan Curzon

Company/ Hospital Name

Gemco

Department

Position

Direct Phone

03458722400

General Phone

0345 872 2400

Opera Account

00020099

Email

Ryan.Curzon@gemco.co.uk

Order Number

Date Received

22/Nov/2021

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Warranty

Returned to  
Supplier  
Cg Dec 2021

Notes 18/Nov/2021 Sarah Walton

18/Nov/2021 Sarah Walton

Faulty sensors to return -

7 x S/N: V104433/34/32/39/45/42/35

All from RVM133032-1

Customer says that there may be more to be returned but unsure at the moment. Will return these 7 units for now

22/Nov/2021 Robert Connor

Received 7 x R22AVG s/n V104432, V104433, V104434, V104435, V104439, V104442, V104445.

Ready For quote

Repair Complete Signed

CCNEEN 17-1-2022

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34352	Oxygen Sensor	0110182	V104432	Yes
SRN34353	Oxygen Sensor	0110182	V104433	Yes
SRN34354	Oxygen Sensor	0110182	V104434	Yes
SRN34355	Oxygen Sensor	0110182	V104435	Yes
SRN34356	Oxygen Sensor	0110182	V104439	Yes
SRN34357	Oxygen Sensor	0110182	V104442	Yes
SRN34358	Oxygen Sensor	0110182	V104445	Yes

0140013 x 7  
Old S/N, SRS, SRN'S

0110182 x 7  
New S/N, SRS, SRN'S

UPS x 1 @ FOC.



Brearley Works, Luddendenfoot, Halifax, West Yorkshire HX2 6JB  
Tel: 0844 24 98 100  
Unit 11, Road One, Winsford Industrial Estate, Winsford, Cheshire CW7 3PL  
Tel: 0844 24 98 102

No. 08407

18/11/21.

GOODS HAVE TODAY BEEN DISPATCHED AGAINST  
THE UNDERMENTIONED ORDER, IN ACCORDANCE  
WITH THE PARTICULARS GIVEN BELOW

TO		GOODS DESPATCHED TO		QUOTE INVOICE NUMBER ON ALL CORRESPONDENCE	
VIAM 5 15 STATION ROAD CROSSHILLS KEIGHLEY BD20 7DT					
				ORDER COMPLETE YES NO	
SPR. No.	JOB/SOF No.	DATE			
CONSIGNEE PER	CARRIAGE	CUSTOMER NAME			
ITEM	QUANTITY	DESCRIPTION			LOCATION
	7	FAULTY 02 CELLS RETURNED UNDER WARRANTY			
		SER NO - V104433 - VOLTAGE RISES TO 15mv IN USE			
		SER NO - V104434 - VOLTAGE RISES TO 13.4mv IN USE			
		SER NO - V104432 - VOLTAGE RISES TO 13.6mv IN USE			
		SER NO - V104439 - 02 NOT GOING BELOW 0.1			
		SER NO - V104445 - 02 NOT GOING BELOW 0.1			
		SER NO - V104442 - 02 NOT GOING BELOW 0.1			
		SER NO - V104435 - 02 NOT GOING BELOW 0.1			
		* ALL FROM P/O X.			
		149896.			
		RETURN REF: SRSG8004			
PICKED BY K. Smith		PACKED BY		DESPATCHED BY	

ALL GOODS ARE CONSIGNEE FROM THE COMPANY'S WORKS PROPERLY INSPECTED, PASSED AND PACKED IN GOOD CONDITION, LOSS OR DAMAGE MUST BE REPORTED WITHIN THREE DAYS OF RECEIPT AND NON-DELIVERY WITHIN TEN DAYS OF DISPATCH BOTH TO THE COMPANY AND THE CARRIERS. THE COMPANY CANNOT ACCEPT ANY LIABILITY FOR ANY LOSS OR DAMAGE WHICH MAY OCCUR IN TRANSIT UNLESS THIS PROVISION IS STRICTLY COMPLIED WITH.

Ref: QD.049  
Issue: 9  
Date: 05/11



## Service Repair Sheet 68004

Contact Name	Ryan Curzon
Company/ Hospital Name	Gemco
Direct Phone	03458722400
General Phone	0345 872 2400
Opera Account	00020099
Email	Ryan.Curzon@gemco.co.uk
Date Received	22/Nov/2021
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34352	0110182	V104432	Oxygen Sensor	

Time :0 Hour(s)

### Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V104588

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34353	0110182	V104433	Oxygen Sensor	

Time :0 Hour(s)

### Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V104589

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34354	0110182	V104434	Oxygen Sensor	

Time :0 Hour(s)

### Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V104590

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34355	0110182	V104435	Oxygen Sensor	

Time :0 Hour(s)

### Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V104591

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34356	0110182	V104439	Oxygen Sensor	

Time :0 Hour(s)

### Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V104592

Service Repair Sheet 68004

Contact Name	Ryan Curzon
Company/ Hospital Name	Gemco
Direct Phone	03458722400
General Phone	0345 872 2400
Opera Account	00020099
Email	Ryan.Curzon@gemco.co.uk
Date Received	22/Nov/2021
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34357	0110182	V104442	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110182    Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V104593

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34358	0110182	V104445	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110182    Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V104594

---