

Service Repair Sheet 68055
Contact Name Apostolos Atsalakis
Company/ Hospital Name XHALE S.A.
General Phone +30 693 660 9908
Opera Account 00006401
Email apostolos@endomedical.co
Date Received 12/Jan/2022
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34553	0110081	661680	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703702

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34554	0110081	667931	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N: 703704

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34555	0110081	672003	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703700

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34556	0110081	672006	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703709

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34557	0110081	672014	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703710

Service Repair Sheet 68055
Contact Name Apostolos Atsalakis
Company/ Hospital Name XHALE S.A.
General Phone +30 693 660 9908
Opera Account 00006401
Email apostolos@endomedical.co
Date Received 12/Jan/2022
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34558	0110081	672020	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703711

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34559	0110081	672022	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703712

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34560	0110081	672029	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703718

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34561	0110081	672030	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703719

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34562	0110081	681646	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703720

Service Repair Sheet 68055
Contact Name Apostolos Atsalakis
Company/ Hospital Name XHALE S.A.
General Phone +30 693 660 9908
Opera Account 00006401
Email apostolos@endomedical.co
Date Received 12/Jan/2022
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34563	0110081	684318	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703721

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34564	0110081	684394	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703722

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34565	0110081	684401	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703723

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34566	0110081	684403	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703725

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34567	0110081	684409	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703730

Service Repair Sheet 68055
Contact Name Apostolos Atsalakis
Company/ Hospital Name XHALE S.A.
General Phone +30 693 660 9908
Opera Account 00006401
Email apostolos@endomedical.co
Date Received 12/Jan/2022
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34568	0110081	684413	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703732

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34569	0110081	684418	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703734

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34570	0110081	684421	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703735

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34571	0110081	684425	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703740

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34572	0110081	684427	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703741

Service Repair Sheet 68055

Contact Name	Apostolos Atsalakis
Company/ Hospital Name	XHALE S.A.
General Phone	+30 693 660 9908
Opera Account	00006401
Email	apostolos@endomedical.co
Date Received	12/Jan/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34573	0110081	684428	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703742

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34574	0110081	684431	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703743

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34575	0110081	684442	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703745

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34576	0110081	689226	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703747

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34577	0110081	689227	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110081 Oxygen sensor UFO 130-2

Replaced in advance of sensors being evaluated for route cause analysis. Replaced with S/N:703750

