Service Repair Sheet SRS68048

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company Type Return Date Promised to Return: 01 Jan 1970 -3600

Steve Bennett

Walsall Manor Hospital NHS Trust

EBME Department

Specialist Medical Engineer

01922 721 172

00005210

steven.bennett@walsallhealthcare.nhs.uk

20/Jan/2022

Robert Connor

Viamed

Warranty

Notes 18/Jan/2022 Steve Hardaker

18/Jan/2022 Steve Hardaker

Returning a Max-48, s/n GL67501002.

Failing to calibrate on a All 2000A monitor (I verified it should be the correct sensor). He has tried it on another monitor and changing the cable and is sure it s the sensor.

Please test ASAP as customer urgently requires a replacement.

19/Jan/2022 Steve Hardaker

On way. TNT shipment number 207065620.

20/Jan/2022 Robert Connor

Received 1 x MAX-48 s/n GL67501002

Ready For quote

Repair Complete Signed

CGreen 31-1-2022

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34651	Oxygen Sensor	0110439	GL67501002	Yes

0140013 × 1 0 FOC old 5/N, 5RS, 5RN

0110439 x 1 FOC New SIN, SRS.

UPS X 1 FOC



