

Service Repair Sheet 68044

Contact Name	Ryan Curzon
Company/ Hospital Name	Gemco
Direct Phone	03458722400
General Phone	0345 872 2400
Opera Account	00020099
Email	Ryan.Curzon@gemco.co.uk
Date Received	19/Jan/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34633	0110182	V103942	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Rising output during use >15 mV. Replaced under warranty with S/N V105021

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34634	0110182	V104654	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

11.4 in air and 53.9 in oxygen. Rising output during use >15 mV. Replaced under warranty with S/N V105020
