

Service Repair Sheet 68048

Contact Name	Steve Bennett
Company/ Hospital Name	Walsall Manor Hospital NHS Trust
Department	EBME Department
Position	Specialist Medical Engineer
General Phone	01922 721 172
Opera Account	00005210
Email	steven.bennett@walsallhealthcare.nhs.uk
Date Received	20/Jan/2022
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34651	0110439	GL67501002	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110439    Oxygen sensor MAX-48.

Replaced under warranty with S/N GM77301003

---