

Service Repair Sheet SRS68057

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Andrew Bullock

Company/ Hospital Name

Furness General Hospital

Department

Medical Engineering

Position

Senior Medical Engineer

Direct Phone

01229 491116

General Phone

01229 870 870

Opera Account

00002471

Email

andrew.bullock@mbht.nhs.uk

Order Number

UHMB1158959

Date Received

02/Feb/2022

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Warranty

Notes 27/Jan/2022 Sarah Walton

27/Jan/2022 Sarah Walton

From customer - We received a number of MAXO2+AE analysers recently and have begun installing them. We have begun installing them and have found a fault with one of the O2 cells (it displays inaccurate readings).

The SN of the faulty O2 cell is GG63299097

The PO number for the order is UHMB1158959

02/Feb/2022 Robert Connor

Received 1 x MAX-250E s/n GG63299097

Ready For quote

Repair Complete Signed

CGreen 4.2.2022

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34669	Oxygen Sensor	0110429	GG63299097	Yes

~~001~~  
0140013 x 1 FOC  
Old S/N, SRS, SRN

0110429 x 1 FOC  
New S/N, SRS, SRN

UPS x 1 FOC.

Company registered in England, No. 01291765.

E-mail Disclaimer

-----  
The information in this email is confidential and may be legally privileged.  
It is intended solely for the addressee. Access to this email by anyone else is unauthorized.  
If you are not the intended recipient, any disclosure, copying, distribution or any action taken or omitted to be taken in reliance on it, is prohibited and may be unlawful.

If you feel you have received this email in error or would like to be removed from our mailing list, please reply with delete in the subject line or call +44 (0)1535 634542  
-----

----- Forwarded message -----

From: **Andrew Bullock** <[andrew.bullock@mbht.nhs.uk](mailto:andrew.bullock@mbht.nhs.uk)>  
Date: Thu, 27 Jan 2022 at 08:09  
Subject: UHMB1158959  
To: [order@viamed.co.uk](mailto:order@viamed.co.uk) <[order@viamed.co.uk](mailto:order@viamed.co.uk)>  
Cc: Rowena Lines <[Rowena.Lines@mbht.nhs.uk](mailto:Rowena.Lines@mbht.nhs.uk)>

Good morning,

We received a number of MAXO2+AE analysers recently and have begun installing them. We have begun installing them and have found a fault with one of the O2 cells (it displays inaccurate readings).

The SN of the faulty O2 cell is GG63299097  
The PO number for the order is UHMB1158959

Please could you provide a replacement O2 cell so we can use the device?

Kind regards,

Andrew

*Andrew Bullock*

Senior Medical Engineer

Medical Engineering

FGH / WGH

☎ 01229 491116 / 01539 716614

*I am unavailable on Mondays.*

*Click [HERE](#) to report any non-urgent device faults.*

Service Repair Sheet 68057

Contact Name	Andrew Bullock
Company/ Hospital Name	Furness General Hospital
Department	Medical Engineering
Position	Senior Medical Engineer
Direct Phone	01229 491116
General Phone	01229 870 870
Opera Account	00002471
Email	andrew.bullock@mbht.nhs.uk
Order Number	UHMB1158959
Date Received	02/Feb/2022
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34669	0110429	GG63299097	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1    0110429    Oxygen sensor MAX-250E

Replaced under warranty with S/N GL79099184

---