

Service Repair Sheet SRS68067

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Ryan Curzon

Company/ Hospital Name

Gemco

Department

Position

Direct Phone

03458722400

General Phone

0345 872 2400

Opera Account

00020099

Email

Ryan.Curzon@gemco.co.uk

Order Number

Date Received

09/Feb/2022

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Warranty

Notes 07/Feb/2022 Sarah Walton

07/Feb/2022 Sarah Walton

Returning 3 faulty sensors.

Raising above 13mV when on use.

V104742

V103503

V104924

09/Feb/2022 Robert Connor

Received 3 x R22AVG s/n V104742, V104882, V104924.

Ready For quote

Repair Complete Signed

CCgreen 10.2.2022.

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34694	Oxygen Sensor	0110182	V104742	Yes
SRN34695	Oxygen Sensor	0110182	V104882	Yes
SRN34696	Oxygen Sensor	0110182	V104924	Yes

0140013 x 3 FCC  
old S/N's ~~SRN~~ SRS, SRN.

0110182 x 3 FCC.  
new S/N's SRS, SRN

UPS x 1 FCC

**EMCO**  
SERVICE

Brearley Works, Luddendenfoot, Halifax, West Yorkshire HX2 6JB  
Tel: 0844 24 98 100  
Unit 11, Road One, Winsford Industrial Estate, Winsford, Cheshire CW7 3PL  
Tel: 0844 24 98 102

GOODS HAVE TODAY BEEN DISPATCHED AGAINST  
THE UNDERMENTIONED ORDER, IN ACCORDANCE  
WITH THE PARTICULARS GIVEN BELOW

TO		GOODS DESPATCHED TO		QUOTE INVOICE NUMBER ON ALL CORRESPONDENCE	
VLAMED LTD 15 STATION ROAD CROSSHILLS KEIGHLEY, WEST YORKSHIRE BD20 7DT.					
SPR. No.		JOB/SOF No.		DATE	
CONSIGNEE PER		CARRIAGE		CUSTOMER NAME	
ITEM	QUANTITY	DESCRIPTION			LOCATION
		* RETURNS REF: SES 68067. ✓			
	3x	2 - 22AVG OXYGEN SENSORS.			
V104882. - Received. Phoned customer to advise to change their paperwork. cy 10-2-22		SN: V104924 - RISES ABOVE 13MV.			
		SN: V103503 - RISES TO 13.5MV.			
		SN: V104742 - RISES ABOVE 13MV.			
		FAULTY AS ABOVE WORKSHOP DIAGNOSIS. TO BE REPLACED UNDER WARRANTY.			
PICKED BY		PACKED BY		DESPATCHED BY	

ALL GOODS ARE CONSIGNEE FROM THE COMPANY'S WORKS PROPERLY INSPECTED, PASSED AND PACKED IN  
GOOD CONDITION, LOSS OR DAMAGE MUST BE REPORTED WITHIN THREE DAYS OF RECEIPT AND NON-DELIVERY  
WITHIN TEN DAYS OF DISPATCH BOTH TO THE COMPANY AND THE CARRIERS. THE COMPANY CANNOT ACCEPT ANY  
LIABILITY FOR ANY LOSS OR DAMAGE WHICH MAY OCCUR IN TRANSIT UNLESS THIS PROVISIO IS STRICTLY  
COMPLIED WITH.

Ref: QD.049  
Issue: 9  
Date: 05/11



Service Repair Sheet 68067

Contact Name	Ryan Curzon
Company/ Hospital Name	Gemco
Direct Phone	03458722400
General Phone	0345 872 2400
Opera Account	00020099
Email	Ryan.Curzon@gemco.co.uk
Date Received	09/Feb/2022
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34694	0110182	V104742	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N 105322

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34695	0110182	V104882	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N 105323

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34696	0110182	V104924	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N 105324

---