

Service Repair Sheet SRS68013

Date Promised to Return: 01 Jan 1970 -3600

Contact Name

Sean Bunn

Company/ Hospital Name

Luton & Dunstable Hospital

Department

Clinical Engineering

Position

Direct Phone

01582718369

General Phone

01582 497042

Opera Account

00003490

Email

Sean.Bunn@ldh.nhs.uk

Order Number

Date Received

07/Dec/2021

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Quote

with
Supplier

Notes 24/Nov/2021 Zoey Teal

24/Nov/2021 Zoey Teal

Sending in a Capnograph to repair and recalibrate. It is showing Flash Error when turned on and the Gas Percentage is low when using the service menu.

Serial number: 80640160

07/Dec/2021 Robert Connor

1 x VM2500S s/n 80640160, with silicone cover and 4 x AA battery.

Ready For quote

CGN0007 8.2.2022.

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34381	Capnograph	4410520	80640160	N

44400000 x 1 @ £90 per hr. Time 1/4 hr @ £22.50.

4480520 x 1 @ £150 Mistake used wrong
capnograph calibration
~~4480500 x 1 @ £150~~ number CG 14.2.22.

SRS, SRN

UPS x 1 £10