

Service Repair Sheet SRS68068

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Date Promised to Return: 01 Jan 1970 -3600

Ryan Curzon

Gemco

03458722400

0345 872 2400

00020099

Ryan.Curzon@gemco.co.uk

10/Feb/2022

Robert Connor

Viamed

Warranty

Notes 09/Feb/2022 Sarah Walton

09/Feb/2022 Sarah Walton

Returning another two sensors

S/N: V105020 and V105021.

He has asked me to ask SH to advise him on whether we are experiencing the same problems with the R-22A sensors as they may change over to these. Will pass this message on to SH

10/Feb/2022 Robert Connor

Received 2 x R22AVG s/n V105020, V105021.

Ready For quote

Repair Complete Signed

CGNEEN 17-2-22.

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34734	Oxygen Sensor	0110182	V105020	Yes
SRN34735	Oxygen Sensor	0110182	V105021	Yes

0140013 x 2 FOC

Old S/N'S SRS'S, SEN'S

0110182 x 2 FOC

New S/N'S, SRS'S, SEN'S

UPS x 1 FOC

MCO
SERVICE

Brearley Works, Luddendenfoot, Halifax, West Yorkshire HX2 6JB
Tel: 0844 24 98 100

Unit 11, Road One, Winsford Industrial Estate, Winsford, Cheshire CW7 3PL
Tel: 0844 24 98 102

No. 09550

GOODS HAVE TODAY BEEN DISPATCHED AGAINST
THE UNDERMENTIONED ORDER, IN ACCORDANCE
WITH THE PARTICULARS GIVEN BELOW

TO		GOODS DESPATCHED TO		QUOTE INVOICE NUMBER ON ALL CORRESPONDENCE	
LIAMED LTD. 15 STATION ROAD CLOSSHILLS KEIGHLEY, WEST YORKSHIRE. RD20 7DT.					
SPR. No.		JOB/SOF No.		DATE	
CONSIGNEE PER		CARRIAGE		CUSTOMER NAME	
ITEM	QUANTITY	DESCRIPTION			LOCATION
	1x	RETURNS REF: SES68068			
	1x	SN: VIOS020 - OXYGEN CELL -			
		SN: VIOS021 - OXYGEN CELL -			
		R-22 AVG - RISES ABOVE 14.44V			
		X 13.5V WHEN IN USE			
		REPLACEMENT REQUIRED UNDER WARRANTY.			
		THANKS			
		RYAN			
PICKED BY		PACKED BY		DESPATCHED BY	

ALL GOODS ARE CONSIGNEE FROM THE COMPANY'S WORKS PROPERLY INSPECTED, PASSED AND PACKED IN GOOD CONDITION, LOSS OR DAMAGE MUST BE REPORTED WITHIN THREE DAYS OF RECEIPT AND NON-DELIVERY WITHIN TEN DAYS OF DISPATCH BOTH TO THE COMPANY AND THE CARRIERS. THE COMPANY CANNOT ACCEPT ANY LIABILITY FOR ANY LOSS OR DAMAGE WHICH MAY OCCUR IN TRANSIT UNLESS THIS PROVISION IS STRICTLY COMPLIED WITH.

Ref: QD.049
Issue: 9
Date: 05/11

UPS x 1 FOC

Service Repair Sheet 68068

Contact Name	Ryan Curzon
Company/ Hospital Name	Gemco
Direct Phone	03458722400
General Phone	0345 872 2400
Opera Account	00020099
Email	Ryan.Curzon@gemco.co.uk
Date Received	10/Feb/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34734	0110182	V105020	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V105325

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34735	0110182	V105021	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

Replaced under warranty with S/N V105326
