

0110182  
LVM130519-1  
LVM130593-1

Helen ONLY  
Please credit  
S/N P102907 PIN 01103  
S/N P100279 PIN 01103  
under warranty, r

Service Repair Sheet SRS68069

Date Promised to Return: 01 Jan 1970 -3600 replacem

Contact Name

Stephen Machin

Company/ Hospital Name

Prosol UK Sales & Distribution Ltd

Department

Purchasing/Sales

Position

Operations Manager

Direct Phone

01142557700

General Phone

0114 2557700

Opera Account

00020046

Email

stephen@prosol.co.uk

Order Number

Date Received

09/Feb/2022

Booked in By

Robert Connor

Main Company

Viamed

Type Return

Warranty

as only buy in  
for forward  
orders. cg 22.2

Do not quote  
for out of  
warranty  
sensors.

Notes 09/Feb/2022 Robert Connor

09/Feb/2022 Robert Connor

3 x R22AVG s/n V104378, V104387, V104388, 3 x R22A s/n 413775, 625186, 653954, 3 x GOC5223 s/n P102037, P102195, P102907, 1 x GOC5230 s/n P100279, 1 x GOC5223 s/n P103073, not faulty, just received open.

Ready For quote

CGNEEN 21.2.22.

Repair Complete Signed

CGNEEN 22.2.22.

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN34680	Oxygen Sensor	0110182	V104378	Yes
SRN34681	Oxygen Sensor	0110182	V104387	Yes
SRN34682	Oxygen Sensor	0110182	V104388	Yes
SRN34683	Oxygen Sensor	0110122	413775	N x
SRN34684	Oxygen Sensor	0110122	625186	Yes
SRN34685	Oxygen Sensor	0110122	653954	Yes
SRN34686	Oxygen Sensor	0110365	P102037	N
SRN34687	Oxygen Sensor	0110365	P102195	N
SRN34688	Oxygen Sensor	0110365	P102907	Yes
SRN34689	Oxygen Sensor	0110365	P103073	Yes
SRN34690	Oxygen Sensor	0110364	P100279	Yes

Credit.

Credit

Replacements  
Return to Supp  
Dispose ASK for  
to kill led  
no rep  
No fault found  
OK.  
Failed - special  
out of warranty  
Faulty - Special  
No fault found  
Special  
faulty. etc.  
Return to Soft

0140013 x 3 -> SRN 34680-34682  
old S/N, SRS, SRN

0110182 x 3  
New S/N, SRS, SRN

0140016 x 3 - SRN. 34683, 34686-34687.  
S/N, SRS's, SRN  
as faulty disposed of as requested FOC  
by customer.

0140011 x 3 - SRS 34684, 34685, 34689 FOC  
S/N, SRS, SRN - no fault found

0140017. x 2  
faulty under warranty  
to be credited.  
S/N's, SRS's, SRN  
TVM13593-1 1 SRN 346  
TVM13519-1 346  
UPS x 1 FOC.

Prosol UK Sales & Distribution Ltd

14-16 Gleadless Road

Sheffield

South Yorkshire

S2 3AB

4<sup>th</sup> February 2022

Account No. 00020046

F.A.O. Return Department

Herewith,

Sensors that have been sent back to us by our customers claiming faulty;

3 x R-22AVG sensor no.s V104378, V104387, V104388 (as per email conversation with Steve Hardaker, sensors showing too high a voltage and didn't drop)

3 x R-22A sensor no.s 413775, 625186, 653954

3 x GOC5223 sensor no.s P102037, P102195, P102907

1 x GOC5230 sensor no. P100279

Also 1 x GOC5223 received open, sensor no. P103073 – please check this is ok.

Please rectify and replace F.O.C. or advise

Many thanks

Steve Machin

Operations Manager



## Service Repair Sheet 68069

Contact Name	Stephen Machin
Company/ Hospital Name	Prosol UK Sales & Distribution Ltd
Department	Purchasing/Sales
Position	Operations Manager
Direct Phone	01142557700
General Phone	0114 2557700
Opera Account	00020046
Email	stephen@prosol.co.uk
Date Received	09/Feb/2022
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34680	0110182	V104378	Oxygen Sensor	

Time :0 Hour(s)

## Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

eplaced under warranty with S/N V105327

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34681	0110182	V104387	Oxygen Sensor	

Time :0 Hour(s)

## Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

eplaced under warranty with S/N V105328

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN34682	0110182	V104388	Oxygen Sensor	

Time :0 Hour(s)

## Parts Replaced

Qty: 1 0110182 Oxygen sensor - Automotive R-22AVG

eplaced under warranty with S/N V105329

---

Repair	Ref	S/N	Equipment Type	End Of Life
SRN34683	0110122	413775	Oxygen Sensor	Time :0 Hour(s)

## Parts Replaced

Qty: 1 0110122 Oxygen sensor - Automotive R-22A

isposed of.

## Service Repair Sheet 68069

Contact Name	Stephen Machin
Company/ Hospital Name	Prosol UK Sales & Distribution Ltd
Department	Purchasing/Sales
Position	Operations Manager
Direct Phone	01142557700
General Phone	0114 2557700
Opera Account	00020046
Email	stephen@prosol.co.uk
Date Received	09/Feb/2022
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type		Under Warranty
SRN34684	0110122	625186	Oxygen Sensor	No Fault Found	
				Time :0 Hour(s)	

this sensor is no fault found.

Repair	Ref	S/N	Equipment Type		Under Warranty
SRN34685	0110122	653954	Oxygen Sensor	No Fault Found	
				Time :0 Hour(s)	

this sensor is no fault found.

Repair	Ref	S/N	Equipment Type		
SRN34686	0110365	P102037	Oxygen Sensor	End Of Life	
				Time :0 Hour(s)	

disposed of

Repair	Ref	S/N	Equipment Type		
SRN34687	0110365	P102195	Oxygen Sensor	End Of Life	
				Time :0 Hour(s)	

disposed of

Repair	Ref	S/N	Equipment Type		Under Warranty
SRN34688	0110365	P102907	Oxygen Sensor		
				Time :0 Hour(s)	

credit to be arranged for this sensor.

Repair	Ref	S/N	Equipment Type		Under Warranty
SRN34689	0110365	P103073	Oxygen Sensor	No Fault Found	
				Time :0 Hour(s)	

tested and working then resealed

Service Repair Sheet 68069

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Date Received

Booked in By

Stephen Machin

Prosol UK Sales & Distribution Ltd

Purchasing/Sales

Operations Manager

01142557700

0114 2557700

00020046

stephen@prosol.co.uk

09/Feb/2022

Robert Connor

---

Repair

Ref

S/N

Equipment Type

Under Warranty

SRN34690

0110364

P100279

Oxygen Sensor

Time :0 Hour(s)

redit to be arranged for this sensor.

---